

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**


【書類名】

図面

Terufumi HARA et al. Q80576
CONNECTOR
Filing Date: March 19, 2004
Darryl Mexic 202-663-7909
1 of 12

図1

Fig.1




4: 接続端子
10: コネクタ
11: ハウジング
11a: 端子収容室
11b: 外周壁
11c: 隔壁(外壁)
11d: 溝部

12: 係止部
12a: 開口部
12b: 側壁(外壁)
12c: 一端面
12d: 第1係止突起
12e: 他端面
12f: 第2係止突起
12g: 空洞部

~~SECRET~~

Terufumi HARA et al. Q80576
CONNECTOR
Filing Date: March 19, 2004
Darryl Mexic 202-663-7909
2 of 12


Fig-2



【図3】

Terufumi HARA et al. Q80576
CONNECTOR
Filing Date: March 19, 2004
Darryl Mexic 202-663-7909
3 of 12

Fig.3




【図4】

Terufumi HARA et al. Q80576
CONNECTOR
Filing Date: March 19, 2004
Darryl Mexic 202-663-7909
4 of 12

Fig. 4

11h: 第1係止突起
12j: 他端面
12m: 係止突起
12r: 係止突起
12s: 係止突起

11: カウジング
11a: 第1係止部
11f: 第2係止部
12: 係止部材
12e: 側壁(外壁)
12g: 端面



【図6】






Fig. 6

【附】






整理番号-P044123

【図9】

Fig. 9



整理番号 P 0 4 4 1 2 3

【図10】

Fig. 10





Fig. 11



~~【図12】~~

Fig. 12

